S-Series V3.0.15 Release Notes

November 2022

Issues fixed since V2.6.1 in V3.0.9

- Unassigning a channel from an active Spill Set no longer pulls down the fader belonging to the channel to the left of the channel being unassigned.
- DMI Mic card now recalls correct gain values after a power cycle.

Issues fixed since V3.0.9 in V3.0.11

- Improves DMI MADI card discovery/communication to address an intermittent issue on some systems where the DMI MADI card could lose connection to racks and, in some cases, incorrectly initiate a DMI card firmware update.

Issues fixed since V3.0.11 in V3.0.14

- Saving a session after creating multiple snapshots will not cause long saving times.
- Recalling a session with a MADI device connected no longer recalls an incorrect input gain for a channel.
- Adjusting an input channel's gain value via MADI is now stable.
- A3232 Stage Racks no longer need to be re-conformed when losing connection with a console.
- Dante gain value now remains displayed on the channel strip when un-routing and then re-routing an input within Dante Controller.

Issues fixed since V3.0.14 in V3.0.15

- Update snapshot button wasn't being displayed when expected in the snapshot view.